


©2023 Moen Incorporated

建议定期清洗产品，以保证其外观光洁明亮。
使用酸性清洁剂清洗附近物品时，有可能损害产品表面，请加倍小心。



A perspective diagram of a rectangular bar with a length of 600mm. The bar has four longitudinal holes. The first hole is 100mm from the left end, and the last hole is 100mm from the right end. The distance between the centers of the first and last holes is 400mm. The bar is shown in a perspective view, with the length dimension labeled as 600.

A perspective diagram of a long, thin rectangular assembly, likely a conveyor belt or a long container. It features two cylindrical rollers mounted on top, one near each end. A dimension line with arrows at both ends is positioned below the assembly, indicating a total length of 1208 mm.

ACC9948

(1) - (5) 情况之一的, 需酌情收取修理费用:

1. 不能出示相符的保修卡和有效购买凭证情况的,
2. 未按使用说明告知的使用方法和注意事项造成的故障,
3. 自行拆卸、维修、改装所造成的故障和损坏,
4. 由于不可抗力等外部原因引起的故障和损坏,
5. 由于运输、装卸、挤压等造成的损坏。


对于保修期外或不在保修范围内的产品，如需维修，摩恩将酌情收取上门费、人工费及材料费。本保修条款仅对原始消费者和酒店行业的购买者有效，并不适用于本产品工业、商业、贸易和非酒店行业的使用。

如对本保修条款内容有任何疑问，请拨打400 630 8866 咨询热线，或向当地经销商咨询。

Fortune Brands Innovations (Shanghai) Co.
Room 207, Building 4, No.1, Lane 1800, Xinyang Highway
China (Shanghai) Pilot Free Trade Zone

MOEN® 摩恩

Telescopic Towel Bar



PLEASE CONTACT MOEN FIRST
For Installation Help, Missing or Replacement Parts
(China) 400-630-8866
www.moen.cn

©2023 Moen Incorporated

CAUTIONS:



MOEN® 摩恩 Bathroom products are made with superb technology to ensure high quality, beautiful and durable.
Be careful when cleaning the product to avoid damage to the surface of the product.
Please clean the surface of the product with water or neutral detergent, and then dry it with a soft towel;

Do not use chemical or corrosive cleaners or rough cloths.


It is recommended to clean the product regularly to ensure its appearance is bright and clean.
When using acidic cleaners to clean nearby items, it may damage the surface of the product.
Please be extra careful.

Installation Instructions:


1. Drill one group of $\phi 6$ 40mm-deep hole in the installation position.
2. Put the two expansion sleeves into the hole, the end face is flush with the wall.
3. Use self-tapping screws to lock the base to the installation position.
4. Install the whole set of accessories, and lock the base with an inner hexagon wrench.



Contraction State



Tensile State



ACC9948

MOEN LIMITED WARRANTY

We offer limited warranty and lifetime maintenance for Moen products, which are all manufactured with high standards of workmanship.

The period of warranty shall start from the date of purchase of the product (according to the invoice or receipt issued by Moen distributors) and shall cover a period of the following: the warranty period for bathroom accessory is 1 year.

This warranty is your coverage against material and workmanship malfunction or defects in Moen products or components. During the warranty period, we offer free main tenance and changing of malfunctioned products or product components. Moen's after sales service liability is limited to the maintenance of faulty items and does not cover your other losses caused by product malfunction, except for other wise stipulated by law.

Cosmetic damages (scratches, dents, etc.) and malfunction or defects caused by abuse or improper maintenance is not covered by this warranty. Although the warranty period remains valid, in case of the following conditions (1) - (5), the maintenance cost (material cost and labor cost) shall still be charged as the case may be:

1. Corresponding warranty card and valid invoice cannot be presented;
2. Faults were caused by the incompliance with the instructions and precautions provided in the user's manual;

3. Damages and faults were caused by self-actuated dismantling, repair and refit;
4. Faults and damages were caused by external factors such as force majeure;
5. Damages were caused by transportation, unloading and extrusion, etc.

This warranty is valid for the original consumers only (including hotel use), and excludes industrial and commercial use of the product (except for hotel use). This card is only responsible for product maintenance rather than any other liabilities.

In the event that the product requires maintenance but exceeds the warranty period, or that the product is not covered by this warranty, labor cost and material cost shall be charged as the case may be.

Please call 400-630-8866 or contact local dealer for any question.

MOEN® 摩恩

合格证
Compliance Certification

产品名称 伸缩毛巾杆
Product Name Telescopic Towel Bar

检验员
Inspector

生产日期
Date of Production

富俊汇源科技(上海)有限公司
中国(上海)自由贸易试验区新杨公路
1800弄1号4幢207室
邮编: 201413

Fortune Brands Innovations (Shanghai) Co., Ltd.
Room 207, Building A, No.1, Lane 1800, Anyang Highway,
China (Shanghai Pilot Free Trade Zone)